

# User guide

## MULTIFUNCTION DIGITAL PRESSURE INSTRUMENT SDM



# User Guide


MULTIFUNCTION DIGITAL PRESSURE INSTRUMENT SDM

---

# PASSWORD

## ENTRANCE PASSWORD


ACCESS PASSWORD TO THE INSTRUMENT MENU' - SEE MENÙ 62 PAGE 52



Password established by the constructor and available for the user

## CALIBRATION PASSWORD

ACCESS PASSWORD TO THE CALIBRATION MENU' - SEE MENÙ 2 PAGE 23



Password established by the constructor and not removable

## Index

<b>1. INTRODUCTION</b>	<b>6</b>
1.1 IMPORTANT INFORMATION	6
1.2 SAFETY INFORMATION	6
<b>2. PRODUCT DESCRIPTION</b>	<b>7</b>
2.1 MAIN INSTRUMENT FEATURE	7
2.2 DISPLAY	7
2.3 PROGRAMMING KEYPAD	8
<b>3. TECHNICAL DATA</b>	<b>9</b>
3.1 RANGES	9
3.2 FEATURES	9
3.3 LABEL	10
<b>4. INSTALLATION</b>	<b>10</b>
4.1 PROCESS CONNECTION	10
4.2 ELECTRIC CONNECTION	11
4.3 CONNECTION ELECTRICAL DIAGRAM	12
<b>5. CALIBRATION AND START-UP</b>	<b>12</b>
5.0.1 MAIN MENU ENTRY	12
5.0.2 MENU SCREEN FOR PRESSURE GAUGE SET UP	14
5.1 DISPLAY SET	16
5.1.1 <i>DIGIT RESOLUTION – Set-up of digit resolution</i>	16
5.1.2 <i>LCD INTEGR – Measure integration set up</i>	17
5.1.3 <i>SECOND MEAS – Second measure display set up</i>	18
5.1.4 <i>TEMPERATURE – Temperature measure unit choice</i>	19
5.1.5 <i>INIT MEASURE – Set-up of re-initialisation of measurement</i>	20
5.1.6 <i>BACKLIGHT – Set-up of BACKLIGHT lighting</i>	21
5.1.7 <i>CLEAR ERROR – Error cancellation</i>	22
5.2 USER CALIB	23
5.2.1 <i>CAL PRESS – Pressure calibration</i>	23
5.2.2 <i>CAL NO PRESS – Calibration without pressure</i>	25
5.2.3 <i>REINIT ALL – Instrument reset function</i>	27
5.3 ANALOG OUT MA	31
5.3.1 <i>OUT TYPE – Analogue output set up</i>	31
5.3.2 <i>LIMIT LOW – Lower limit set up</i>	32
5.3.3 <i>LIMIT HIGH – Higher limit set up</i>	33
5.3.4 <i>OUT INTEGR – Analogical output integration set up</i>	34
5.4 SWITCH AL1	35
5.4.1 <i>TFINCI – Alarm set up</i>	35
5.4.2 <i>RSP1 – Lower limit start point set up</i>	38
5.4.3 <i>SP1 – Upper limit start point set up</i>	39
5.4.4 <i>TCONT1 – Configuration set-up</i>	40
5.4.5 <i>RDSP1 – Setup delay time intervention point lower limit</i>	41
5.4.6 <i>RDSP1 – Set up delay time intervention point upper limit</i>	42

5.5 SWITCH AL2	43
5.5.1 <i>TFINC2 – Alarm set up</i>	43
5.5.2 <i>RSP2 – Lower limit start point set up</i>	46
5.5.3 <i>SP2 – Upper limit start point set up</i>	47
5.5.4 <i>TCONT2 – Configuration set up</i>	48
5.5.5 <i>RDSP2 – Set-up of delay time intervention point lower limit</i>	49
5.5.6 <i>DSP2 – Set up of delay time intervention point upper limit</i>	50
5.6 SERVICE	51
5.6.1 <i>LANGUAGE – Language set up</i>	51
5.6.2 <i>PASSWORD EN – Instrument password identification process</i>	52
5.6.3 <i>SYSTEM TEST – Instrument function test</i>	53
5.6.4 <i>MODEL – Viewing model instrument</i>	54
5.6.5 <i>HW SW VERS – Viewing version hardware and software</i>	55
5.6.6 <i>CALIBRATION – Viewing date of calibration</i>	56
5.6.7 <i>SERIAL N – Viewing serial number</i>	57
5.6.8 <i>WORKED H – Viewing worked hours</i>	58
5.6.9 <i>LAST ERROR – Viewing last error</i>	59
<b>6. ALARM SIGNALS</b>	<b>60</b>
6.1 <i>ALARM SIGNAL DESCRIPTION</i>	60
<b>7. APPENDIX</b>	<b>61</b>
7.1 <i>DIMENSION</i>	61
7.2 <i>TABLE SHOWING EQUIVALENCE OF UNITS OF MEASUREMENT</i>	62

## 1. Introduction

### 1.1 Important information

**Please carefully read this information before the installation and use of the instrument. Keep it in a safe and accessible place for every user.**

The safety level of the instrument depends on the choosing the correct application, the proper installation of the instrument and by following the maintenance procedures established by the manufacturer.

Technicians in charge of the instrument selection, installation and maintenance should be able to understand if the instruments condition could affect its function and thereby, lead to any premature damage or breaking.

It is essential that these procedures are included in the plants regulations and should be carried out by a qualified staff.

Any improper use could damage the instrument, causing breakage and possible hazards to the staff and to the plant.

In order correctly choose the right instrument it is highly recommended to reference the most recent catalogue sheets available on-line at [www.nuovafima.com](http://www.nuovafima.com)



In accordance with directive  
EMC 2004/108/CE – PED 97/23/CE

Standards of reference: EN 61326  
IEC 60770 – IEC 61298-2

### 1.2 Safety information



Warning

- The manufacturer disclaims all responsibility in case of damages caused by the improper use of the product and by the non-respect of the instructions reported in this manual.
- Follow carefully the specific safety rules in case of measuring oxygen pressure, acetylene, inflammable or toxic gas or liquids.
- Disconnect the instruments only after depressurization of the system.
- The process fluids residuals in the disassembled instruments could affect people, the environment and the system. It is highly recommended to take proper precautions.



Attention


- Before installation be sure that the right instrument has been selected following the working conditions and in particular the range, the working temperature and the compatibility between the material used and the process fluid.
- This manual does not concern the instruments conforming to standard 94/9/CE (ATEX).
- The product warranty is no longer valid in case of non-authorized modifications and of wrong use of the product.
- The user is totally responsible for the instrument installation and maintenance.
- Handle and carefully stock the instrument used for toxic or inflammable liquids measurement

## 2. Product description


### 2.1 Main instrument feature

The digital multifunction instrument SDM can be used to measure and to control pressure. Thanks to a wide choice of scale ranges and processes connection it can be used in the following industrial sectors: food industry, canning industry pharmaceutical, petrochemical, conventional plants.

The instruments components are:



### 2.2 Display



#### Graphic bar

The graphic bar shows the zero point and the calibration full scale for the instrument. The segment extension of the graphic bar displayer shows the zero and the full scale range crossing of the instrument.

#### Value measured

Viewing of pressure value measured with resolution from 1 to 5 digits

#### Unit of measurement and setting menu

Viewing of unit of instrument calibration measurement and dialogue window of setting menus

The following are available

- unit of pressure - BAR,mBAR,AT,KPA,MPA,PSI,KG/CM2,MH2O,CMH2O,MMH2O,MMHG,INHG
- unit of measurement not for pressure - MM,M,FEET,INCH,L,KG,T,M3,GAL,LB,%

#### Information and data input

Viewing of information and data entry dialogue window:

- minimum and maximum
- ambient temperature, minimum temperature and maximum temperature
- analogue output signal

# User Guide

MULTIFUNCTION DIGITAL PRESSURE INSTRUMENT SDM


## Alarms

Viewing of status of alarm thresholds AL1 and AL2

Setting available:

- Hysteresis
- Window

## 2.3 Programming keypad



### **ON/esc key**

- Exits the menu or submenu
- Enters the settings menu when pressed at the same time as OK

### **OK key**

- Confirms the data entered and alters the instrument settings
- Enters settings menu pressed at the same time as esc

### **UP and DOWN keys**

- Keys to move in order to select the desired function
- increase (SU) and decreases (GIU') the value entered



### 3. Technical data

#### 3.1 Ranges

Nominal range	Minimal extension scale	Set zero	Offset	Overpressure	Breakage
-0,1...0,4 bar	20%	-0,1...0 bar	±20%	0,8 bar	1,2 bar
-0,4...1,6 bar	20%	-0,4...0 bar	±10%	3,2 bar	4,8 bar
-1...6 bar	20%	-1...0 bar	±8%	12 bar	18 bar
-1...16 bar	20%	-1...0 bar	±4%	32 bar	48 bar
-1...40 bar	20%	-1...0 bar	±2%	80 bar	120 bar
-1...100 bar	20%	-1...0 bar	±2%	200 bar	300 bar
-1...250 bar	20%	-1...0 bar	±2%	375 bar	500 bar
-1...400 bar	20%	-1...0 bar	±2%	600 bar	800 bar
-1...1000 bar	50%	-1...0 bar	±2%	1100 bar	1200 bar
-1...1600 bar	50%	-1...0 bar	±2%	1700 bar	1800 bar

#### 3.2 Features

##### Electrical feature

Analogue signal on output	<i>4...20mA, with separate power source (3 wires)</i>
Electrical connection	<i>Coupling cable box in accordance with VDE regulations, with pigtail outlet or screened cables <math>\phi 7...13\text{mm}</math>. Protection against inversion of polarity and short-circuit</i>
Alarm thresholds	<i>n°2, PNP o NPN, programmable</i>
Input	<i>Power supply 11...30 VDC</i>

##### Mechanical features

Process connection	<i>Threaded process connection 1/2" Gas o 1/2" NPT In stainless steel AISI 316 L</i>
Sensor	<i>Piezoresistive for range <math>\leq 400</math> bar with o-ring in NBR (optional: FPM-EPDM-CR) thin film in stainless steel for range <math>&gt; 400</math> bar</i>
Case	<i>Stainless steel, aired for pressure <math>\leq 100</math>bar</i>
Ring	<i>Stainless steel</i>
Keyboard	<i>Polyester</i>
Protection degree	<i>IP 65 according IEC 529/ EN 60529-1</i>


# User Guide

MULTIFUNCTION DIGITAL PRESSURE INSTRUMENT SDM

## Temperature of use

Ambient temperature	-4... +158°F (-20... 70°C)
Process fluid temperature	-4... +176°F (-20... 80°C)
Compensated temperature range	+32... +176°F (0... 80°C)

## 3.3 Label




## 4. Installation

### 4.1 Process connection

Tighten the threaded portion of the instrument, applying a torque (max 30Nm) using a suitable spanner on the hexagonal part of the process connector, without applying force to the case with your hands.


For attachments to the process with cylindrical threads (GAS – metric), a head gasket made from material compatible with measurement fluid or gas, must be used. If the attachment thread is conical.

If the attachment thread is conical, the seal should, instead, be created by simply tightening the grip. To improve thread hold a PTFE strip of the male thread.




If the instrument is equipped with a fluid separator, the grip by which to tighten the attachment, must be carried out on the latter and not on the instrument itself, as this may affect calibration.

## 4.2 Electric connection



1 – Dismount the connector as in the figure



2 – Connect cable (see figure) remount the connector and fix it on the instrument





The IP degree according to the normative EN 60529-1:1992 is guaranteed only if the female connector, together with the connection cable, is mounted on the instrument and its components are mounted correctly

# User Guide

MULTIFUNCTION DIGITAL PRESSURE INSTRUMENT SDM

## 4.3 Connection electrical diagram



Input	11...30 VDC
Analogue input	4...20mA
Analogue output charge	$R_L \leq (V_{in} - 11) / 0,02$
Alarm thresholds	PNP-NPN
Thresholds Energy capacity	2 x 600mA*
Absorbed energy	< 100mA + thresholds energy


\*single function PNP o NPN function available only




Use shielded cable

## 5. Calibration and start-up

### 5.0.1 Main menu entry



To enter the main menu press simultaneously ON/esc and OK as shown in the picture






Use UP and DOWN keys to select the desired menu page, as shown in the figure, and press OK

## 5.0.2 Menu screen for pressure gauge set up





Instrument menu entry through password if activated, after digit confirm it through “PASSWORD OK” at page 3 – for activation see page 60



4	SWITCH AL1	 Use UP and DOWN keys to select the desired sub-menu	41 TFUNC1	Page 34
			42 RSP1	Page 37
			43 SP1	Page 38
			44 TCONT1	Page 39
			45 RDSP1	Page 40
			46 DSP1	Page 41
			5	SWITCH AL2
42 RSP2	Page 45			
43 SP2	Page 46			
44 TCONT2	Page 47			
45 RDSP2	Page 48			
46 DSP2	Page 49			
6	SERVICE	 Use UP and DOWN keys to select the desired sub-menu	61 LANGUAGE	Page 50
			62 PASSWORD	Page 51
			63 SYSTEM TEST	Page 52
			64 MODEL	Page 53
			65 HW SW TEST	Page 54
			66 CALIBRATION	Page 55
			67 SERIAL N	Page 56
			68 WORKED H	Page 57
69 LAST ERROR	Page 58			
7	EXIT			

## 5.1 DISPLAY SET

### 5.1.1 DIGIT RESOLUTION – Set-up of digit resolution



### *i* Digit resolution



Available setup options

<b>AUTORANGE</b>	Automatically sets the decimal digit after the point
<b>9.9999</b>	Four digits after point
<b>99.999</b>	Three digits after point
<b>999.99</b>	Two digits after point
<b>9999.9</b>	One digit after point
<b>99999.</b>	No digit after point



## 5.1 DISPLAY SET

### 5.1.2 LCD INTEGR – Measure integration set up





### *i* Display integration

By selecting one of the values available, the update time of the measurement seen is increase or decreased

## 5.1 DISPLAY SET

### 5.1.3 SECOND MEAS – Second measure display set up





### *i* Viewing of second measurement

Viewing available

<b>NO</b>	No measure displayed
<b>P MIN</b>	Measure minimum pressure
<b>P MAX</b>	Measure maximum pressure
<b>T AMBIENT MAX</b>	Minimum ambient temperature measured
<b>T AMBINET MAX</b>	Maximum ambient temperature measured
<b>CURRENT</b>	Electrical Energy measure

## 5.1 DISPLAY SET

### 5.1.4 TEMPERATURE – Temperature measure unit choice



### *i* Temperature measure unit choice



Unit of measurement available Celsius – Fahrenheit

**Celsius**  $(T^{\circ}\text{F}-32)\times 5/9$

**Fahrenheit**  $9/5\times T^{\circ}\text{C}+32$

## 5.1 DISPLAY SET

### 5.1.5 INIT MEASURE – Set-up of re-initialisation of measurement





### *i* Measurement reinitialisation shown

Starting up the INIT MEASURE function the instrument starts the reading of the measure previously detected  
**PM – Pm – TAM – TAM**

## 5.1 DISPLAY SET

### 5.1.6 BACKLIGHT – Set-up of BACKLIGHT lighting





### *i* Backlight lighting

By selecting from the various time available, the back light lighting time is defined  
Times available: ON – OFF – 1 – 5 – 10 – 15 – 30 – 60 – 120

## 5.1 DISPLAY SET

### 5.1.7 CLEAR ERROR – Error cancellation



### Error cancellation

This function cancels from the display all error signals visualized


## 5.2 USER CALIB

### 5.2.1 CAL PRESS – Pressure calibration





#### USER CALIB menu entry


Entry calibration **PASSWORD** – SEE PAGE 3  
after digit confirm it through






# User Guide

MULTIFUNCTION DIGITAL PRESSURE INSTRUMENT SDM



	<p align="center"><b>MINIMUM SCALE RANGE VALUE SET UP</b></p> <p>Use the UP and DOWN keys, select NO or APPLY to proceed with the confirmation of the minimum scale value</p>	
---	---	--

	<p align="center">NO exit menu APPLY proceeds by confirmation of the offset value</p>	
--	---	---

	<p align="center"><b>MAXIMUM SCALE RANGE VALUE SET UP</b></p> <p>Use the UP and DOWN keys, select NO or APPLY to proceed with the confirmation of the maximum scale value</p>	
---	---	--

	<p align="center">NO exit menu APPLY proceeds by confirmation of the offset value</p>	
--	---	---

<p align="center">Unit of pressure measurement</p>	<p align="center">   <i>Attention</i> </p>	<p align="center">Unit of measurement not for pressure</p>
--	--	--

	<p align="center"><b>FULL SCALE RANGE VALUE OF REFERENCE SET UP</b></p> <p>Use the UP and DOWN arrows to increase or decrease the value or OK (advance one place) or ESC (back one place). Press OK on an empty place to memorize the data entered</p>	
---	--	---

**2 USER CALIB**



**21 CAL PRESS**  
Use UP and DOWN keys to select the desired sub-menu

**22 CAL NO PRESS**

**23 REINIT ALL**

**Page 24**

**Page 26**




## 5.2 USER CALIB

### 5.2.2 CAL NO PRESS – Calibration without pressure





#### USER CALIB menu entry

Entry calibration **PASSWORD** – SEE PAGE 3  
after digit confirm it through





# User Guide

MULTIFUNCTION DIGITAL PRESSURE INSTRUMENT SDM

	<b>MINIMUM SCALE RANGE VALUE SET UP</b> Use the UP and DOWN arrows to increase or decrease the value or OK (advance one place) or ESC (back one place). Press OK on an empty place to memorize the data entered	
---	--	--






	<b>MAXIMUM SCALE RANGE VALUE SET UP</b> Use the UP and DOWN arrows to increase or decrease the value or OK (advance one place) or ESC (back one place). Press OK on an empty place to memorize the data entered	
---	--	--



<b>Unit of pressure measurement</b>	 <i>Attention</i>	<b>Unit of measurement not for pressure</b>
-------------------------------------	---	---



	<b>FULL SCALE RANGE VALUE OF REFERENCE SET UP</b> Use the UP and DOWN arrows to increase or decrease the value or OK (advance one place) or ESC (back one place). Press OK on an empty place to memorize the data entered	
---	--	---



<b>2 USER CALIB</b>		<b>21 CAL PRESS</b> → <b>Page 22</b>
		<b>22 CAL NO PRESS</b> Use UP and DOWN keys to select the desired sub-menu
		<b>23 REINIT ALL</b> → <b>Page 26</b>

## 5.2 USER CALIB

### 5.2.3 REINIT ALL – Instrument reset function



**USER CALIB menu entry**  
Entry calibration **PASSWORD** – SEE PAGE 3  
after digit confirm it through




## *i* Information

### Zero offset value set up


Use the function SET P OFFSET to zero the instrument within the limits set out in the table on page 7

#### Example 1: range -1...6 bar (POSITIVE OFFSET)

##### Initial situation




##### For error correction key in -0,5 bar in the window dialogue SET P OFFSET




#### Example 2: range -1...6 bar (NEGATIVE OFFSET)

##### Initial situation




##### For error correction key in -0,25 bar in the window dialogue SET P OFFSET



## *i* Information


### Minimum and full scale range value set up



## *i* Information

### Full range value of reference set up

Entering a measure different from pressure the instrument requires a value to be used as full range reference



### Unit ok measurement set up

The available measure units can be divided into two groups:

#### Unit of pressure

BAR, mBAR, AT, KPA, MPA, PSI, KG/CM2, MH2O, CMH2O, MMH2O, MMHG, INHG,

#### Unit of measurement not for pressure

MM, M, FEET, INCH, L, KG, T, M3, GAL, LB, %



When using the units of measure not related to pressure, a value of base scale reference will be required, except for those given in %



**Changing the unit of measurement zeroes the alarm thresholds limits, setting them to default values**



## 5.3 ANALOG OUT MA

### 5.3.1 OUT TYPE – Analogue output set up



## 5.3 ANALOG OUT MA

### 5.3.2 LIMIT LOW – Lower limit set up





### **i** Limit low set up

This is an alarm function and allows to set the lower value of the analogical output OUT LIMIT LOW



## 5.3 ANALOG OUT MA

### 5.3.3 LIMIT HIGH – Higher limit set up





### i Limit high set up

This is an alarm function and allows to set the lower value of the analogical output OUT LIMIT HIGH

## 5.3 ANALOG OUT MA

### 5.3.4 OUT INTEGR – Analogical output integration set up





### **i** Set-up of integration time analogue output

By selecting of the values available, the integration time of the signal output is increase or decreased.  
Time available: 0,1 – 0,2 – 0,5 – 1 – 2 – 3 – 4 – 5 – 10 – 15 – 20s

## 5.4 SWITCH AL1

### 5.4.1 TFUNC1 – Alarm set up






## **i** Information

### Set-up of alarm function


#### WINDOW

#### WINDOW main features


The window function brings to the contact switch during crossing of points SP1 and RSP1 when the pressure increases or decreases



### PNP





### NPN



## 5.4 SWITCH AL1

### 5.4.2 RSP1 – Lower limit start point set up





### **i** Lower limit start point set up

Value always less than upper limit intervention point (SP1)

## 5.4 SWITCH AL1

### 5.4.3 SP1 – Upper limit start point set up





### Upper limit start point set up

Value always greater than lower limit intervention point (RSP1)

## 5.4 SWITCH AL1

### 5.4.4 TCONT1 – Configuration set-up





## *i* Configuration set up

See page 36 - 37



## 5.4 SWITCH AL1

### 5.4.5 RDSP1 – Setup delay time intervention point lower limit





### Set-up of delay time intervention point lower limit

Defines the time necessary for contact switch. This occurs where the pressure, having passed the switch point, is maintained for a time in excess of that set

## 5.4 SWITCH AL1

### 5.4.6 RDSP1 – Set up delay time intervention point upper limit





### **i** Set up of delay time intervention point upper limit

Defines the time necessary for contact switch. This occurs where the pressure, having passed the switch point, is maintained for a time in excess of that set

## 5.5 SWITCH AL2

### 5.5.1 TFINC2 – Alarm set up




### **i** Information

#### Set up of alarm function


#### HYSTERESIS

#### HYSTERESIS main features


The HYSTERESIS function allows to set up the switch hysteresis between point SP2 and RSP2  
When the increasing pressure reaches the SP2 point the contact switches on  
When the decreasing pressure reaches the RSP2 the contact switches or and returns to its original condition.



#### PNP



#### NPN




## **i** Information

### Set-up of alarm function


#### WINDOW

#### WINDOW main features


The window function brings to the contact switch during crossing of points SP2 and RPS2 when the pressure increases or decreases



### PNP





### NPN



## 5.5 SWITCH AL2

### 5.5.2 RSP2 – Lower limit start point set up





### *i* Lower limit start point set up

Value always less than upper limit intervention point (SP2)

## 5.5 SWITCH AL2

### 5.5.3 SP2 – Upper limit start point set up





### *i* Upper limit start point set up

Value always greater than lower limit intervention (RSP2)

## 5.5 SWITCH AL2

### 5.5.4 TCONT2 – Configuration set up





## *i* Configuration set-up

See page 44 - 45



## 5.5 SWITCH AL2

### 5.5.5 RDSP2 – Set-up of delay time intervention point lower limit





### **i** Set up of delay time intervention point lower limit

Defines the time necessary for contact switch. This occurs where the pressure, having passed the switch point, is maintained for a time in excess of that set

## 5.5 SWITCH AL2

### 5.5.6 DSP2 – Set up of delay time intervention point upper limit





### **i** Set up of delay time intervention point upper limit

Defines the time necessary for contact switch. This occurs where the pressure, having passed the switch point, is maintained for a time in excess of that set



## 5.6 SERVICE

### 5.6.1 LANGUAGE – Language set up





## 5.6 SERVICE

### 5.6.2 PASSWORD EN – Instrument password identification process




## 5.6 SERVICE

### 5.6.3 SYSTEM TEST – Instrument function test



## 5.6 SERVICE

### 5.6.4 MODEL – Viewing model instrument



## 5.6 SERVICE

### 5.6.5 HW SW VERS – Viewing version hardware and software

**65 HW SW VERS**  
version hardware and software

61 LANGUAGE → Page 50

62 PASSWORD EN → Page 51

63 SYSTEM TEST → Page 52

64 MODEL → Page 53

SERVICE ←



**65 HW SW VERS**  
Use UP and DOWN keys  
to select the desired sub-menu

66 CALIBRATION → Page 55


67 SERIAL N → Page 56

68 WORKED H → Page 57

69 LAST ERROR → Page 58

## 5.6 SERVICE


### 5.6.6 CALIBRATION – Viewing date of calibration





## 5.6 SERVICE

### 5.6.7 SERIAL N – Viewing serial number



## 5.6 SERVICE

### 5.6.8 WORKED H – Viewing worked hours

**68 WORKED H**  
worked hours

61 LANGUAGE → Page 50

62 PASSWORD EN → Page 51

63 SYSTEM TEST → Page 52

64 MODEL → Page 53

65 HW SW VERS → Page 54

66 CALIBRATION → Page 55

67 SERIAL N → Page 56

**68 WORKED H**  
Use UP and DOWN keys  
to select the desired sub-menu

69 LAST ERROR → Page 58

SERVICE




## 5.6 SERVICE

### 5.6.9 LAST ERROR – Viewing last error

**69 LAST ERROR**  
-

61 LANGUAGE	→	Page 50
62 PASSWORD EN	→	Page 51
63 SYSTEM TEST	→	Page 52
64 MODEL	→	Page 53
65 HW SW VERS	→	Page 54
66 CALIBRATION	→	Page 55
67 SERIAL N	→	Page 56
68 WORKED H	→	Page 57



The following error cannot be cancelled

## 6. Alarm signals

### 6.1 Alarm signal description

Displayed errors	Description
<b>MAX HI PRESS</b>	Signalling of exceeding upper breakage limit
<b>OVER HI PRESS</b>	Signalling of exceeding upper overpressure limit
<b>OUT HI PRESS</b>	Signalling of exceeding upper calibration limit
<b>OUT LOW PRESS</b>	Signalling of exceeding lower calibration limit
<b>OVER LOW PRESS</b>	Signalling of exceeding lower overpressure limit
<b>MAX LOW PRESS</b>	Signalling of exceeding lower breakage limit

Displayed errors	Description
<b>OUT HI LIMIT</b>	Signalling of exceeding upper limit analogue output
<b>OUT LOW PRESS</b>	Signalling of exceeding lower limit analogue output


Displayed errors	Description
<b>ERR PM</b>	Read signal not updated for power cut
<b>ERR Pm</b>	Read signal not updated for power cut
<b>ERR TAM</b>	Read signal not updated for power cut
<b>ERR TAm</b>	Read signal not updated for power cut



The visualized errors clearance can be carried out through the menu 17 at the point CLEAR ERROR (see page 22 )

## 7. Appendix

### 7.1 Dimension



7.2 Table showing equivalence of units of measurement

	bar	mbar	at	kPa	MPa	psi	kg/cm <sup>2</sup>	mH <sub>2</sub> O	cmH <sub>2</sub> O	mmH <sub>2</sub> O	mmHg	inHg
bar		1000	0,987	100	0,1	14,5	1,02	10,19	1019,7	10197	750,06	29,53
mbar	1x10 <sup>-3</sup>		9,87x10 <sup>-4</sup>	0,1	1x10 <sup>-4</sup>	0,0145	1,02x10 <sup>-3</sup>	0,0102	1,02	10,20	0,750	0,0295
at	1,013	1013		101,33	0,1013	14,7	1,033	10,33	1033,3	103330	760	29,92
kPa	0,01	10	9,87x10 <sup>-3</sup>		1x10 <sup>-3</sup>	0,145	0,0102	0,1019	10,19	101,9	7,50	0,295
MPa	10	10000	9,87	1000		145	10,20	101,9	10197	101974	7500	295
psi	0,069	68,94	0,068	6,894	6,89x10 <sup>-3</sup>		0,0703	0,703	70,31	703,1	51,71	2,036
kg/cm <sup>2</sup>	0,098	981	0,96	98,1	0,098	14,22		10	1000	10000	735,56	28,96
mH <sub>2</sub> O	0,098	98,06	0,097	9,81	9,81x10 <sup>-3</sup>	1,42	0,1		100	1000	73,554	2,89
cmH <sub>2</sub> O	9,8x10 <sup>-4</sup>	0,98	9,7x10 <sup>-4</sup>	0,0981	9,8x10 <sup>-5</sup>	0,0142	1x10 <sup>-3</sup>	0,01		10	0,735	0,0289
mmH <sub>2</sub> O	9,8x10 <sup>-5</sup>	0,098	9,7x10 <sup>-5</sup>	9,81x10 <sup>-3</sup>	9,8x10 <sup>-6</sup>	1,42x10 <sup>-3</sup>	1x10 <sup>-4</sup>	1x10 <sup>-3</sup>	0,1		0,0735	2,89x10 <sup>-3</sup>
mmHg	1,33x10 <sup>-3</sup>	1,333	1,31x10 <sup>-3</sup>	0,13	1,33x10 <sup>-4</sup>	0,0193	1,3x10 <sup>-3</sup>	0,013	1,359	13,59		0,039
inHg	0,034	33,86	0,033	3,386	3,38x10 <sup>-3</sup>	0,491	0,0345	0,345	34,53	345,32	25,4	



**NUOVA FIMA**

Via C. Battisti, 59/61 – 28045 INVORIO (No) – Italy  
Tel. +39 0322 253200 – Fax +39 0322 253232  
[www.nuovafima.com](http://www.nuovafima.com) – e-mail: [info@nuovafima.com](mailto:info@nuovafima.com)